imitation mullion treatment. The end piers of the facade continue above the eaves line and have brick tops. There are decorative accents of brick and stucco. The suspended awning is of steel construction. Below this, the shopfront of No. 75 appears to retain its original form with a central ingo. No. 77 has been altered but still has a side entrance, alongside which is the entry to the upstairs occupancy.

Modifications: The awning appears to be of fairly recent construction. The shopfront of No. 77 has been largely filled in by brickwork and tiling. The top sashes of No. 75 have been altered to single panes.

319 4811 (02)Godden Mackay Pty Ltd 56 Waterloo Street Surry Hills NSW 2010


| H | RED | THE | D | MATN | STREET | STUDY | 1993 |
|-------|------------|----------|---|------|-----------------|-------|------|
| B-S (| D 85 84 86 | R1 R1. | | VIA | 79 1 10 17, 17, | | |

| Item No. | Page 1 | No. | Addres | s: | 7: | 5 - 77 Da | alhous | sie Street | | | |
|------------------------|------------------|-------|------------|--------|------------|-----------|---------|--------------|-------------------|------------------|-----------|
| 37 | 2/6 | | Name | of Bui | lding: | | | | | | |
| Contributio | n | App | | Con | npatible | | nious | Compatib | | the state of the | isting |
| To Streetsca | ipe: | Sca | le/mass | For | m/shape | Style | | Materials | Colour | Sho | |
| | | | 2 | | 2 | 2 | | 2 | Scheme 4 | | nts -5 |
| | | | 2 | | 2 | 2 | | 4 | ** | ** | -3 |
| | | | 1= Exce | llent | 2= Good | d = 1 | _ | 4= Poor | 5= Disruptive | | |
| Heritage Li | stings | I | LEP | | NT | | AH | С | Heritage Study | | Other |
| Statement o | f Signif | fican | ce: | | | | | | | | |
| harmonic | | | | | | | | • | g to the varied | | |
| Recommenda (a) Immedia | ate: | | | | | me for th | ne foor | ade above t | he awning. If | the n | aint |
| car | inot be | remo | oved from | face | brickwor | k it shou | ld be | overpainted | to match the | brick | colour. |
| (b) Medium Un | | rolle | r blind tr | eatme | nt and sig | gnage. | | | | | |
| (c) Long Te | erm: build th | e sho | opfront o | f No. | 77 to be 0 | compatit | ole wit | th that of N | o. 75. | | |
| Desirable I | Plannin | g Ob | ojectives | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | (n- | | |
| Additional | Comm | ents | : | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

HABERFIELD MAIN STREET STUDY 1993

1993 PHOTOGRAPH

Address: 75 - 77 Dalhousie Street Item No Page No 37 3/6 Name of Building:



Photograph taken by Roll No. 92-084-2 Robert Irving

Neg No.

Frame No. 3

| 37 | 4/6 | Name of Buil | lding: | |
|----|---------|--------------|----------------|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | 1.0 464 | | | |
| | | | 2 (8) | |
| | | | | |
| | | | None Available | |
| | | | Trone Transoc | |
| | | | | |
| | | | | |
| | | | | |
| ~ | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Godden Mackay Pty Ltd 56 Waterloo Street Surry Hills NSW 2010 (02) 319 4811

Date


Photographer

Source

HABERFIELD MAIN STREET STUDY 1993

CONSERVATION ACTION

Godden Mackay Pty Ltd 56 Waterloo Street Surry Hills NSW 2010 (02) 319 4811



Godden Mackay Pty Ltd 56 Waterloo Street Surry Hills NSW 2010 (02) 319 4811