Address: 22, 24 and 28 L	ackey Street		Item No.	Page No.
Name of Building:			55	1/0
Former Name:				
Owner:				
	#			
Lessee/s:		Current Use/s:		
Date of Construction:	Architect:	Builder:		
plan shows two symmetrical brick build building to the south (the present No. 30 Nos. 22 or 24, commensurate with the d been "lost" at some stage during site re-	 This gap has a slightly difference evident in the fr 	y smaller frontage rontage today. No	on the 1890	plan than
References: Water Board Plans. Sands Directories				
Suitas Directories				
Description: A group of three shops with facade of stucco. The shopfronts have a of the original format. No. 28 has a name posted footpath awning; the present awn plain; it originally had two double-hung head and keystone motifs, and a moulded the cornice which provides a base for the supported by paired brackets and surmound bay. This facade closely resembles that	all been altered, though the rower frontage than the orning is a suspended metal windows to each occupated and bracketed string-comparage. The parapet is unted by urns. A modello	at of No. 22 possi thers. There would structure. Above ncy, with decorati ourse at sill level. pierced and divided lion crowns the	ibly gives an ld have been that the facative projecting There is a fried into bays	indication a timber de is g flat-arch ieze below by piers

Modifications: The upper windows of Nos. 22 and 28 have been replaced by metal framed windows in horizontal format, that of No. 28 being at a lower level and breaking the sill string-course.

Item No.	Page No	. Address	: 2	2-26 Lac	key Street		
35	2/6	Name of Building:					
Contributio	n A			Harmon	nious Compatibl	e Existing	Existing
To Streetsca			Form/shape		Materials	Colour	Shop
			0.55	5		Scheme	Fronts
		1	1	1	1	4	4
		1 E 1					
Heritage Lis	tings	I= Excel	lent 2= Good NT	3 = F	air 4= Poor AHC	5= Disruptive	Other
Heritage Las	ungs	LEF	IN I		Anc	Heritage Study	Other
						Study	
Statement o	f Significa	ince:					
An intere potential.	An interestingly-detailed though now somewhat mutilated facade with very good streetscape potential.						
Recommend	lations Fo	r Conserva	tion Action:				
(a) Immediate: Adopt appropriate paint colour and signage schemes.							
(b) Medium Term: Reinstate traditional vertical-format windows in Nos. 22 and 28 and reconstruct the stucco sill							
moi	moulding of No. 28.						
(c) Long Term:							
Consider rebuilding shopfronts with traditional forms, proportions and details.							
Desirable Planning Objectives:							
		*Toronto					
Additional Comments:							

SUMMER HILL MAIN STREET STUDY 1993

1993 PHOTOGRAPH

Address: 22, 24 and 28 Lackey Street Item No 35 3/6



Photograph taken by Robert Irving


Roll No. 92-065-2

Neg No.

Frame No. 2


SUMMER HILL MAIN STREET STUDY 1993

HISTORIC PHOTOGRAPH



SUMMER HILL MAIN STREET STUDY 1993 CONSERVATION ACTION

Address:	22, 24 and 28 Lackey Street	Item No.	Page No.
		35	5/6
Name of Build	ding:		-,-





- 1. STOCKADE TAN all facade above awning.
 2. DEEP BRONZE GREEN awning front.
- 3 RUSTIC PINE. awning soffit, window frames +