Additional Ashfield Heritage Inventory Sheets 2010

Name of Item Other Names	House, 'Denr	mark Cottage'			Reference N° 2011/3
Address Locality	70 Norton Str Ashfield	reet, corner of A	'Beckett Ave	enue 2131	Land Title
Item Type Group Name	Building and	Owner/s			
Statement of Signature 'Denmark Co Ashfield, with and conserved The prope of Norton Stru The house girls coud be burgeoning. The front	Condition as observed from street — Intact Minor alteration — Sympathetic Unsympathetic Major alteration — Sympathetic Major alteration —				
Summary of Si	Rare	Associative	Represen	tative	☐ Unsympathetic Modifications —
Historic Aesthetic					At the time of these inspections the house was undergoing
Social Scientific Other					conservation.
TO TO	ZOS VIII NO PRO		No. 1		



			Survey Date	Surveyed by
Photo Roll N°	Digital	Frame N°	7/1/0011	RI

Additional Ashfield Heritage Inventory Sheets 2010

Reference N°

Residence with new residential development at re Avenue. At the time of writing conservation wor							
Heritage Listing Recommended							
Themes : Local	Themes : State						
Subdivision and consolidation	Towns suburbs and villages						

Historical Notes

Current Use

The brick house called 'Denmark Cottage' was erected by W H Dickinson during or prior to 1879. It was originally shingle-roofed. At the time of its incorporation in 1871 Ashfield contained just over 200 dwellings, 123 of them here in the South Ward. Only 70 of these were brick-walled. During the building boom of the 1880s many of the larger estates were subdivided and by 1889 the South Ward had more than 750 houses. This cottage thus pre-dated the boom.

The property was sold to Miss Jane Turner in 1881 Jane Turner had established a Ladies School at 'Stanley Villa' in Liverpool Road, and she moved her school to 'Denmark Cottage' in 1882, when the development of educational institutions in Ashfield was rapidly increasing. It is not known how long Turner's school lasted, but she lived in the cottage until 1904, from about 1890 sharing it with Miss Frances Bolton. It is possible that the rear wing on the east side was added during Miss Bolton's residency.

In more recent years the house had been superficially altered by such measures as enclosing the front verandah and adding elements at the rear. Until the approval of the additional residential structure at the rear of the property it had fallen into disrepair. At the time of writing the is being conserved appropriately. The photograph above was taken during this project.

Physical Description

The original building of brick with a shingle-covered gable roof, comprised two rooms each side of a central passage, in which was a staircase leading up to two attic rooms flanking the upper hall, which had two central dormer windows, one facing the front and the other facing the rear. On the rear or south there was a brick eastern wing containing two smaller rooms. The skillion-roofed front (north) verandah had brick wing walls, two cast iron columns and a small set of stairs leading up from the front garden, making the street facade symmetrical. A verandah led to the kitchen in the rear wing. A report by Alan Croker of Design 5 Architects revealed that the whole ensemble, along with most of the interior elements such as fireplaces and joinery, survives, although until the present conservation campaign its components were obscured by such things as verandah infillings, additions and the decrepitude of neglect. The roofing had been replaced in earlier years by terra cotta tiles.

At the time of writing a campaign of conservation was in progress, under the guidance of Paul Davies Pty Ltd, architects and heritage consultants.

The rear of the site now contains a new residential structure. Accordingly the boundary of this listing should be the house and its site to the north of the south wall of the rebuilt rear wing of the house.

Information Sources

Records in Council rate books, South Ward; *Sands Directories* for relevant years; S & R Coupe, *Speed the Plough*, pp 103, 107; these and other sources incorporated in research by Helen

Wilson, Heritage Adviser, summarised in reports to Ashfield Council, 30/4/05 and 23/5 06. Reports to Council by Robert A Moore Pty Ltd, Heritage Adviser, 30/11/05 and 24/5/06. Heritage Report (Revised) to Council by Weir & Phillips, architects, February 2006.

Report to Council by Alan Croker of Design 5 Architects, 28/9/06.

Information from the office of Paul Davies Pty Ltd, architect and heritage consultants, January 2011.