Ashfield Heritage Study Review of Areas Zoned 2b & 2c

Name of Iter	n St	rathmore				Reference No
Other Name	S					49
Address	09	Tintern l	Road			Land Title
Locality	Ashi					
Item Type	Gro	up				Zoning
Group Name	2c					
Evaluati	on of S	ignificance	Rare	Associative	Representative	Owner
Historic					lacksquare	Private
Aesthetic					\boxtimes]
Social						
Scientific						Condition
Other						☐ Intact ☐ Minor alteration ☑ Sympathetic alteration
Few of these b	uildin	ngs now su	ırvive. De	espite its alteration	enstruction in Ashfielons, the historical intense the history of this	erest
Photograph						

Negative 13 14

Current Use

Photo roll

1999 - 1

Reference No

Surveyed by:

 TK

Survey Date

12/23/1999

Ashfield Heritage Study Review of Areas Zoned 2b & 2c

Residential			49		
Heritage Listing					
Themes: Local	Themes: State				
Subdivision & consolidation	Housing				
Sub themes: local					
History of the Item					
This villa first appeared in the Sands Dire	ectory in 1889 occupied by Llewelly	n Rudder (o	riginally		
Rutter). It originally had a slate roof. It was built in 1886 for Rutter. His family occupied the house					

Physical Description

until 1918.

Two storey late Victorian villa of rendered and painted masonry construction. Hipped roof now clad with dark terra cotta tiles. Eaves brackets interspersed with roundels above a moulding betray the Italianate origins of this building which has now been altered. Decorative rendered chimneys remain. A colonnaded loggia at the front shields the building from the weather and adds to privacy. The lower part of the colonnade has squared rendered masonry columns supporting the upper level loggia which has squater and thicker columns support the upper roof. A wrought iron grilled gate protects this entrance and gives a faintly Moorish air to what was once an Italianate villa. A moulded multi-panelled door is set within a wide central doorway with side lights and circular fanlight leading into the villa. The front windows are protected with shutters. Above the two sets of front windows is an elaborate plaster ?? . The upper windows on the sides are narrow round arches with double hung sashes. A low modern rendered brick fence is at street level.

Information Sources

Sands, Directories, 1885-92; Ashfield Scrapbook, No 7, 1988, p. 4

Reference No

49

Additional Images

Ashfield Heritage Study Review of Areas Zoned 2b & 2c