ZONE 1 – THE WA	VATERFRONT AND CALLAN POINT		
ITEM No. 6B ORIGINAL NAME: CURRENT USE:		CONSTRUCTION DATE: ARCHITECT / BUILDER:	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6B INDIGE	NOUS VEGETATION	
LOCATION:	GRID: 12,	H2 ZONE: 1	
Oak, Rough Barked Bangalay with poss indigenous shrub (u sp) and areas of Ka Grass, Lomandra a	o of indigenous She b Barked apple and ith possible shrub (unidentified as of Kangaroo		
CONDITION:	Part intact. Modified and simplified communities through disturbance.		ities through disturbance.
HISTORY:	Regenerate	from original species.	
REFERENCES:	1991 DPWS Heritage Study		
SIGNIFICANCE:	Significant as rare remnant of indigenous vegetation and representative components of original setting for the asylum and Garry Owen Estate.		
GUIDELINES:	Maintain. Remove weeds and regenerate/revegetate with seed from indigenous plants. Replace introduced species with indigenous species where appropriate throughout the point area. Encourage development of indigenous plant and animal communities. Note NPWS should be contacted prior to any disturbance on or near Aboriginal midden sites and care should be taken around European carvings to avoid damage.		

CALLAN PARK CONSERVATION MANAGEMENT PLAN

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6C		CONSTRUCTION DATE:	HERITAGE LISTINGS:
ORIGINAL NAME: Aboriginal midder		ARCHITECT / BUILDER:	 National Estate S170 List
CURRENT USE:			 National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6C ABORI	GINAL MIDDENS	
LOCATION:	GRID: 12	ZONE: 1	
DESCRIPTION:			
discarded from me 1971; 45-6-1972. 1481), which is not	Four separate aboriginal shell middens all on NPWS register. Middens are a collection of shells discarded from meals. Midden numbers on NPWS register are: 45-6-283; 45-6-618; 45-6-1971; 45-6-1972. There is one additional area of midden remains o the NPWS Register (45-6-1481), which is not identified here as it is located within fill material on the reclaimed waterfront and thus is believed to be of little heritage value.		
CONDITION:	Varies between intact to unknown levels of intactness.		
HISTORY:	-		
REFERENCES:			
SIGNIFICANCE:	All middens are significant as rare remaining evidence of Aboriginal habitation and provide evidence of pre-European ecology. Site 45-6-283 is of major research value due to its intact profiles, others may be of research value if lower profiles are intact.		
GUIDELINES:	Preserve all middens in accordance with NPWS directions. Carry out an archaeological investigation by a qualified archaeologist prior to any disturbance. Any disturbance of or near Aboriginal sites (such as clearing, revegetating, demolition or construction) must be approved by the National Parks and Wildlife Service in accordance with the NPWS Act 1974. Advice should also be sought from the Metropolitan Local Aboriginal Land Council. The introduction of interpretive signage, possibly in combination with the European rock carvings is recommended. The existing access tracks crossing some middens should be discreetly hidden such as by general revegetation works (with indigenous species). For further reference contact the Australian Museum.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No: 6D ORIGINAL NAME: Rock carvings CURRENT USE:		CONSTRUCTION DATE: ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6D ROCK	CARVINGS	
LOCATION:	GRID: H2,	12-3 ZONE: 1	
DESCRIPTION: Extensive range of including ships, figu globes, fish, an anin (possibly alpaca), h (similar to compass many numerals (po dates) and hand let (some doesn't seer sense. Others pos French).	ures, imal heads, stars s roses) and bessible ttering m to make		
CONDITION:	Exposed carvings intact, some hidden beneath grass and gardens. Some exposed to foot traffic and vandalism.		
HISTORY:	Believed carved by one man who lived on a boat in Iron Cove. Patients may have been responsible for some carvings. It is possible that there were aboriginal carvings on the site but no evidence is visible.		
REFERENCES:	John Clegg. Sydney University. Article "Sydney Rock Art" by John Clegg pp119-122 in <i>The Moving Frontier</i> (edited by Peter Stanbury). Reed. Sydney 1977. <i>Sydney Morning Herald</i> Column 8 item and reply 1960s. J.S. Kerr, <i>Out Of Sight Out Of Mind</i> . 1991 DPWS Heritage Study		
SIGNIFICANCE:	Significant as 'outsider art'; as record of social history; as a rare and exceptional item and as a factor in the local sense of place.		
GUIDELINES:	Preserve in accordance with Burra Charter. Redirect public path away from surface carvings and provide sensitively designed barriers to prevent foot traffic over the carvings. Protect hidden and exposed carvings during any clearing, revegetation, demolition or construction work. Before any disturbance of the area carry out assessment by qualified historical archaeologist. Consider careful installation of interpretive signage.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT				
ITEM No. 6E		CONSTRUCTION DATE:	HERITAGE LISTINGS:	
ORIGINAL NAME: Sea wall and boat wharf		ARCHITECT / BUILDER: Unknown	 National Estate S170 List National Trust 	
CURRENT USE: Sea wall, wharf disused			Leichhardt LEPState Heritage Inventory	
ITEM:	6E SEA WALL & BOAT WHARF			
LOCATION:	GRID: H2, G3 ZONE: 1			

DESCRIPTION:

Battered sandstone block seawall edging land fill areas.



CONDITION:	Generally intact.
HISTORY:	Age of wall unresearched. Possibly early 1900s construction added to or replaced in 1940s to 1960s.
REFERENCES:	1991 DPWS Heritage Study. 1903 photo of original boatshed. Plate 46 Powell. Site plan 1893, Site plan 1931-51, Site plan 1965.
SIGNIFICANCE:	Significance as early site developments reflecting importance of water travel and relationship with Gladesville Hospital.
GUIDELINES:	Restore damaged sections. Retain boat wharf as relic or redevelop for modern use reflective of its original purpose.

ZONE 1 – THE WA	ATERFRONT AND CALLAN POINT		
ITEM No. 6f ORIGINAL NAME: Sewer outlet CURRENT USE: Disused		CONSTRUCTION DATE: Circa 1880 ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6F SEWEF	OUTLET	
LOCATION:	GRID: H2	ZONE: 1	
DESCRIPTION: Ruins of sandstone sewer outfall extending into Iron Cove.			
CONDITION:	In ruined st	In ruined state.	
HISTORY:	Originally asylum sewer discharging into Iron Cove. Later used for stormwater.		Ove. Later used for
REFERENCES:	1991 DPWS Heritage Study. 1877 site plan		
SIGNIFICANCE:	Significant as an item of original asylum design and early sewage system.		gn and early sewage system.
GUIDELINES:	Preserve as ruins.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6G ORIGINAL NAME: CURRENT USE: Stair, retaining wall.		CONSTRUCTION DATE: Circa 1905 ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6G STONE	E STAIRS & WALLS	
LOCATION:	GRID: H2	ZONE: 1	
DESCRIPTION: Dry stone wall and staircase.	stone		
CONDITION:	Intact		
HISTORY:	Likely to have been built in association with swimming pool construction in the mid 1900s.		
REFERENCES:	1991 DPWS Heritage Study. Site plan 1931 and site plan 1965.		and site plan 1965.
SIGNIFICANCE:	No evidence of heritage significance, however sympathetic with development area of the point.		er sympathetic with
GUIDELINES:	Retain and	conserve.	

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6H ORIGINAL NAME: CURRENT USE: Recreational open space		CONSTRUCTION DATE: Circa 1880-1900 ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
BUILDING:	6H LAWN	TERRACE	
LOCATION:	GRID: H2	2-3 ZONE: 1	
DESCRIPTION: Grassed terrace edged by sea wall.			
CONDITION:	Intact but p	oor condition.	
HISTORY:	Reclaimed in 1880s to early 1900s to provide level access to the boat wharf extended in 1960s. Now used as a recreation ground.		
REFERENCES:	1991 DPWS Heritage Study. Site plan 1965		
SIGNIFICANCE:	Original terrace is significant as early access to boat wharf, a significant item in the running of the early asylum. However, extended size and existing use diminish integrity of significance.		
GUIDELINES:	Preserve ad	ccess to boat wharf. Retain as op	en space.

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6 I		CONSTRUCTION DATE: 1930s-1960s	HERITAGE LISTINGS:
ORIGINAL NAME:		ARCHITECT / BUILDER:	National Estate
CURRENT USE:		Unknown	 S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6 I RESIDE	INTIAL AND WARD GARDENS	
LOCATION:	GRID: H1	-2 ZONE: 1	
DESCRIPTION:			

Fenced gardens attached to residences and ward buildings.



CONDITION:	Intact.
HISTORY:	Installed in 1930s to 1960s overlaying rock carvings and rock outcrop.
REFERENCES:	1991 DPWS Heritage Study.
SIGNIFICANCE:	Intrusive on heritage significance of natural landform, vegetation and rock carvings.
GUIDELINES:	Remove. Take care to prevent damage to any European carvings or Aboriginal relics which may be hidden below the soil surface and contact the NPWS if any Aboriginal relics are found.

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6J ORIGINAL NAME: Path CURRENT USE:		CONSTRUCTION DATE: ARCHITECT / BUILDER: Hospital patients	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6J PATH		
LOCATION:	GRID: H3	ZONE: 1	
DESCRIPTION: Sandstone flagged path leading to building B495. Inscribed with date of construction.			
CONDITION:	Fair conditio	on, partly overgrown.	
HISTORY:	-		
REFERENCES:	1991 DPWS Heritage Study.		
SIGNIFICANCE:	Some significance as work of patients illustrating involvement of patients as therapy (or economy!) however not an outstanding or rare example. Path is intrusive on the significant natural character of the point.		
GUIDELINES:	Remove. Pl removal.	notographically record as evidenc	e of patient work prior to

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6K ORIGINAL NAME: CURRENT USE:		CONSTRUCTION DATE: ARCHITECT / BUILDER:	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6K INDIVIE	DUAL TREES	
LOCATION:	GRID: H3	8, 13 ZONE: 1	
Large introduced E and Coral trees and species planted thr	ESCRIPTION: arge introduced Eucalypt d Coral trees and other becies planted throughout eveloped area of the point.		
CONDITION:	Good.		
HISTORY:	Larger trees probably planted in 1930s and 1950s with more recent additions.		1950s with more recent
REFERENCES:	1991 DPWS Heritage Study.		
SIGNIFICANCE:	No identified heritage significance.		
GUIDELINES:		may be incorporated into future nted to alternate location.	development where appropriate

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 6L ORIGINAL NAME: CURRENT USE:		CONSTRUCTION DATE: circa 1960-1970 ARCHITECT / BUILDER:	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	6L POPLAF	R AVENUE	
LOCATION:	GRID: G3	-I 3 ZONE: 1	
DESCRIPTION: Avenue of Lombardy Poplars along Waterfront Drive.			
CONDITION:	Fair.		
HISTORY:	Planted afte	er 1952. Possibly in early 1960s (or 1970s.
REFERENCES:	1991 DPWS Heritage Study. 1952 aerial photo.		oto.
SIGNIFICANCE:	Intrudes on the significant character of the early asylum period.		arly asylum period.
GUIDELINES:	IDELINES: Remove as practicable.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT				
ITEM No. 5B ORIGINAL NAME: CURRENT USE: BUILDING: LOCATION:	5B EMBAN	CONSTRUCTION DATE: 1980s ARCHITECT / BUILDER: Unknown IKMENT PLANTING	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory	
DESCRIPTION:				
Mass planted Hills Weeping fig, Cedar Wattle and other native shrubs (non- indigenous). May provide habitat for Grey-headed Flying Fox, which is threatened in Leichhardt Local Government Area.				
CONDITION:				
HISTORY:	1980s mas	s planting.		
REFERENCES:	1991 DPWS Heritage Study. Photo c. 1903, site inspection		, site inspection	
SIGNIFICANCE:	Highly intrusive of outlook from and setting for cottages B401 and B404.			
GUIDELINES:	Professionally assess significance as habitat for Grey-headed Flying Fox. If not significant as habitat, prune trees to regain views. As trees die remove and revegetate slope with low growing indigenous species such as grasses and groundcovers.			

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 7A ORIGINAL NAME: CURRENT USE: Recreational		CONSTRUCTION DATE: 1880-1942 ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: Ational Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
ITEM:	7A RECLA	IMED LAND	
LOCATION:	GRID: L4	-H4, C4-D4 ZONE: 1	
DESCRIPTION: Flat lawn area now football oval.	v used as View of the second s		
CONDITION:	Intact		
HISTORY:	Area G4-H4 – former swamp and inlet reclaimed for vegetable growing in 1880s to early 1900s and canal formed in early 1900s. Area C4-D4 reclaimed in 1942.		
REFERENCES:	1991 DPWS Heritage Study.		
SIGNIFICANCE:	Early asylum development reflecting the need for large scale food production for asylum subsistence and representative of Charles Moore's design. Edge of reclaimed area reflects part of original shoreline. 1942 reclamation not of heritage significance.		
GUIDELINES:	Preserve. Maintain open character. Future development should reflect original shoreline presently evident as a relatively natural embankment behind the oval, and maintain integrity of significance by revegetating with indigenous species. Current recreational use is sympathetic to significance.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT				
ITEM Nos. 7B ORIGINAL NAME: CURRENT USE:		CONSTRUCTION DATE: ARCHITECT / BUILDER: Unknown	HERITAGE LISTINGS: Autional Estate S170 List National Trust Leichhardt LEP State Heritage Inventory	
ITEM:	7B SEAWA	LL AND CANAL		
LOCATION:	GRID: C4	-G4, F4-5 ZONE: 1		
LOCATION: GRID: C4 DESCRIPTION: Canal with battered sandstone block walls. Originating in Broughton Hall gardens and piped to end of open canal.				
CONDITION:	Substantial	y intact – in need of repair.		
HISTORY:	HISTORY: Seawall age unresearched, likely to span a number of construction ph from early 1900s to 1965. Canal built between 1903 and 1930.			
REFERENCES:	1991 DPWS Heritage Study. Site plan 1903. Aerial photo 1930.		Aerial photo 1930.	
SIGNIFICANCE:	Canal significant as reflection of original creek line and as early asylum development. No fabric of heritage significance.		5 5	
GUIDELINES:	Preserve ca 1900s perio	anal and alignment of early shorel od.	ine established in 1880s to early	

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 7C		CONSTRUCTION DATE:	HERITAGE
ORIGINAL NAME:		ARCHITECT / BUILDER:	LISTINGS: National Estate S170 List
CURRENT USE:		Unknown	 National Trust Leichhardt LEP
			State Heritage Inventory
ITEM:	7C LANDFILLED PLAYING FIELD		
LOCATION:	GRID: C-D, 4-5 ZONE: 1		

DESCRIPTION:

Grassed terrace with steep embankments to a maximum height of 4 metres slightly set back from the seawall.



CONDITION:	Intact but unconsolidated.		
HISTORY:	Result of 1970s dumping of fill.		
REFERENCES:	1991 DPWS Heritage Study		
SIGNIFICANCE:	Highly intrusive		
GUIDELINES:	Ideally remove fill. Alternatively reform embankments to profiles more sympathetic to surrounding landscape. Where opportunity arises utilise this area in future developments sympathetic to the significance of the site.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 7D		CONSTRUCTION DATE:	HERITAGE LISTINGS:
ORIGINAL NAME:		ARCHITECT / BUILDER:	 National Estate S170 List
CURRENT USE:			 National Trust Leichhardt LEP State Heritage Inventory
ITEM:	7D NATUR	AL LANDFORM	
LOCATION:	GRID: E-F	4-5 ZONE: 1	
DESCRIPTION:	N:		
Visible steep slopes only as low rise.	Visible steep slopes edging early land reclamation and area of original low headland discernic only as low rise.		
CONDITION:	Part obscured by existing development.		
HISTORY:			
REFERENCES:	1991 DPWS Heritage Study. Site plan 1877		
SIGNIFICANCE:	Evidence of the natural landform adds to the significance of the Point and reflects the original landscape context for the asylum and Garry Owen Estate.		
GUIDELINES:	Future development should reflect shape of natural shoreline.		

ZONE 1 – THE WATERFRONT AND CALLAN POINT				
ITEM No. 7E ORIGINAL NAME:		CONSTRUCTION DATE: 1900s-1965 ARCHITECT / BUILDER:	HERITAGE LISTINGS:	
CURRENT USE:			 National Trust Leichhardt LEP State Heritage Inventory 	
ITEM:	7E ROAD PATTERN			
LOCATION:	GRID: G3-4 ZONE: 1			

DESCRIPTION:

Waterfront Drive is bitumen with no kerb and gutter. Other roads all kerbed and guttered bitumen roads.



CONDITION:	Intact
HISTORY:	Waterfront Drive overlays original early 1900s track. Others built as access roads to Repatriation Works from 1918 to 1965.
REFERENCES:	1991 DPWS Heritage Study. Site plans 1903, 1931-51, 1965.
SIGNIFICANCE:	Waterfront Drive alignment is significant as original asylum access track. No evidence of heritage significance for other roads. Generally complexity of later roads intrudes upon significant character.
GUIDELINES:	Preserve alignment of Waterfront Drive in future layouts but not necessarily as a road. Refer to open space management plan.

ZONE 1 – THE WATERFRONT AND CALLAN POINT				
ITEM No.7M ORIGINAL NAME: Norfolk Island hibiscus CURRENT USE:		CONSTRUCTION DATE: Planted 1880s-1890s ARCHITECT / BUILDER: Charles Moore	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory	
ITEM:	7M NORFO	OLK ISLAND HIBISCUS		
LOCATION:	GRID: F4-	G4 ZONE: 1		
DESCRIPTION: Row with some of original trees missing.				
CONDITION:	Fair to goo	d		
HISTORY:	Planted late 1880s to 1890s along newly formed shoreline.			
REFERENCES:	1991 DPWS Heritage Study.			
SIGNIFICANCE:	Significant as original asylum plantings representing the species selection of Charles Moore.			
GUIDELINES:	Maintain. Remove carparking from beneath trees. Carry out tree surgery and improve growing conditions. Replant missing trees.			

ZONE 1 – THE WATERFRONT AND CALLAN POINT			
ITEM No. 7N ORIGINAL NAME: CURRENT USE: ITEM: 7N WILLOW		CONSTRUCTION DATE: Planted mid 1970s-mid 1980s ARCHITECT / BUILDER:	HERITAGE LISTINGS: National Estate S170 List National Trust Leichhardt LEP State Heritage Inventory
LOCATION:	GRID: H4-	-G5 ZONE: 1	
DESCRIPTION: Double row willows on eastern edge of oval and screen planting partially covering front of Buildings B496 and B497.			
CONDITION:	Generally g	ood. Some poor specimens.	
HISTORY:	Willow rows planted in 1970s. Willow screen planting in front of repatriatic wards planted in mid 1980s.		n planting in front of repatriation
REFERENCES:	1991 DPWS Heritage Study.		
SIGNIFICANCE:	No heritage significance. Partially dense canopies hide significant former shoreline and physically isolate oval area from remainder of site. Intrusive original asylum scheme.		
GUIDELINES:	Over time replace with indigenous tree groups sympathetic to the landscape character of the early 1900s seen in plates 70, 72 and 83 in Powell.		